This document is classified as **White** in accordance with the Panel Information Policy. Information can be shared with the public, and any members may publish the information, subject to copyright.

MP106 'CHIMSM update for Unknown WAN Variant'

Conclusions Report – version 0.1

About this document

This document summarises the responses received to the Modification Report Consultation.

Summary of conclusions

Modification Report Consultation

Four responses were received to the Modification Report Consultation. Three believe the modification should be approved. They considered the modification better facilitates SEC Objectives (a), (c) and (g).

Modification Report Consultation responses

Summary of responses

Four responses were received to the Modification Report Consultation. Three respondents believed the modification should be approved, and one felt it should be rejected.

The respondents that believed the modification should be approved cited that the modification better facilitates SEC Objectives (a), (c) and (g). The rationale given was that the Proposed Solution offers clear instructions for how Users should interpret the " " Space response.

One respondent felt that the modification should be rejected as they felt that providing the guidance to Appendix I 'CH Installation and Maintenance Support Materials' Table 3 is unnecessary.

One of the respondents that believed the modification should be approved provided further comments that the correct name of the SEC document is 'SEC Appendix I – CH Installation & Maintenance Support Materials''. This has been noted by SECAS and the necessary changes have been made. They also commented that it is unclear why an update to the DCC User Guidance was not considered.