

Duncan Stone  
Department of Business, Energy and Industrial Strategy  
1 Victoria Street  
London  
SW1H 0ET

21<sup>st</sup> May 2020

**DCC Public**

Dear Duncan

I would like to bring to your attention to errors in the Eligible Product Combination List (EPCL) entries in the EPCL Report 2 that DCC submitted to BEIS for approval on 29 April 2020. DCC has established that the report contained incorrect values for the CPL hardware version.version and CPL hardware version.revision fields of the PPMID specification in EPCL entries 000021 and 000022 listed in Annex A. The table below contains the correct information.


DCC identified the error when attempting to add these entries onto the EPCL following BEIS approval of these EPCL entries. As a result of this, EPCL entries 000021 and 000022 have not been added to the EPCL and DCC can accordingly confirm there is no risk of incorrect migrations taking place.

It should be noted that following the typographic error in EPCL entries reported to BEIS in December 2019, the changes DCC put in place have been followed, specifically the second change to reconcile the data received in the letter from BEIS against the actual EPCL/CPL entry. It was the reconciliation that exposed the error in EPCL entries 000021 and 000022 and enabled DCC to avoid adding incorrect entries onto EPCL. This demonstrates that the changes put in place are effective in avoiding incorrect EPCL entries.

In the letter of December 2019 DCC proposed a change to include a second DCC internal review prior to submission of data to BEIS. DCC has commenced a lessons learned exercise to define further changes to make the second review more robust.

DCC would like to add the correct versions of the EPCL entries as soon as possible, accordingly, DCC requests that you direct DCC to add entries 000021 and 000022 to the EPCL with the corrections as described in the table below, in terms of Clause 3.7 SEC Appendix AL – Transition and Migration Approach Document.

Regards

A handwritten signature in blue ink, appearing to be 'Richard Cooper', on a light-colored background.

**Richard Cooper**

Head of Demand and Logistics

07917 565051

[richard.cooper@smartdcc.co.uk](mailto:richard.cooper@smartdcc.co.uk)



Equivalent EPCL Index		N/A	N/A
Proposed EPCL Entry Index		000021	000022
Combination_ID		3 - CH+ESME+GSME+PPMID	3 - CH+ESME+GSME+PPMID
S1SP ID		CGI	CGI
Group ID		CA	CA
Dormant/Active Indicator		Active only	Dormant only
CH Device Model	CPL_manufacturer_identifier	10:57	10:57
	Manufacturer_Name	Elster/Honeywell	Elster/Honeywell
	CPL_model_identifier	01:10	01:10
	Model	AM110R	AM110R
	CPL_hardware_version.version	01	01
	Hardware Version	01	01
	CPL_hardware_version.revision	10	10
	Hardware Revision	10	10
	CPL_firmware_version	2EDBE509	2EDBE509
	Firmware Version	03.07.09 (49) - REV09	03.07.09 (49) - REV09
	CPL_GBCS_version_number	GBCS Version 0.0	GBCS Version 0.0
	CPL_Manufacturer_Image_creator		
	CPL_Manufacturer_Image_hash	2CA4A444F94883C702A1F874 B08814FDC20509AF2DE217C3 6282D5E04C86830E	2CA4A444F94883C702A1F874 B08814FDC20509AF2DE217C3 6282D5E04C86830E
	CPL_Manufacturer_Image_description		
	SMSO ID	CGI Instant Energy	CGI Instant Energy
	Existing WAN Provider ID	Vodafone	Vodafone
ESME Device Model	CPL_manufacturer_identifier	10:57	10:57
	Manufacturer_Name	Elster/Honeywell	Elster/Honeywell
	CPL_model_identifier	03:00	03:00
	Model	AS300P	AS300P
	CPL_hardware_version.version	01	01
	Hardware Version	01	01
	CPL_hardware_version.revision	01	01
	Hardware Revision	01	01
	CPL_firmware_version	0401D8C9	0401D8C9
	Firmware Version	ASP 04.04.01-55497	ASP 04.04.01-55497
	CPL_GBCS_version_number	GBCS Version 0.0	GBCS Version 0.0
	CPL_Manufacturer_Image_creator		
	CPL_Manufacturer_Image_hash	EC9E8111584FDAE88912DE2C DD9C01E646000C217BCF14A BF4955B8799B0E284	EC9E8111584FDAE88912DE2C DD9C01E646000C217BCF14A BF4955B8799B0E284
	CPL_Manufacturer_Image_description		
	CPL_Manufacturer_Image_creator		
GSME Device Model	CPL_manufacturer_identifier	10:57	10:57
	Manufacturer_Name	Elster/Honeywell	Elster/Honeywell
	CPL_model_identifier	05:73	05:73
	Model	BK-G4E EI2	BK-G4E EI2
	CPL_hardware_version.version	00	00
	Hardware Version	00	00
	CPL_hardware_version.revision	00	00
	Hardware Revision	00	00
	CPL_firmware_version	00000446	00000446
	Firmware Version	0.10.94	0.10.94
	CPL_GBCS_version_number	GBCS Version 0.0	GBCS Version 0.0
	CPL_Manufacturer_Image_creator		
	CPL_Manufacturer_Image_hash	F16809038A5B00827AC75EFA F869C55DD5CDA63E1BEC747 AD542BD9B1702FA58	F16809038A5B00827AC75EFA F869C55DD5CDA63E1BEC747 AD542BD9B1702FA58
	CPL_Manufacturer_Image_description		
	CPL_Manufacturer_Image_creator		
PPMID Device Model	CPL_manufacturer_identifier	10:E0	10:E0
	Manufacturer_Name	Chameleon	Chameleon
	CPL_model_identifier	00:03	00:03
	Model	IHD3-MS	IHD3-MS
	CPL_hardware_version.version	05	05
	Hardware Version		
	CPL_hardware_version.revision	00	00
	Hardware Revision		
	CPL_firmware_version	00020700	00020700
	Firmware Version	2.07.00	2.07.00
	CPL_GBCS_version_number	GBCS Version 0.0	GBCS Version 0.0
	CPL_Manufacturer_Image_creator		
	CPL_Manufacturer_Image_hash		
	CPL_Manufacturer_Image_description		
	CPL_Manufacturer_Image_creator		
IHD	Manufacturer_Name		
	Model		